

# VDE螺丝刀套装

#### 603CS6VDE



#### 配置文件



### 产品属性

Set includes:

- 4x electrician's screwdriver with insulated blade VDE (article 603VDE) dim. 0.4x2.5x75, 0.8x4.0x100, 1.0x5.5x125, 1.2x6.5x150
- 2x crosstip (PH) screwdriver with insulated blade VDE (article 613VDETBI) dim. PH 1x80, PH 2x100

| 产品名称        | SKU    | 文章        | 尺寸   | 数量 |
|-------------|--------|-----------|--|----|
| VDE螺丝刀套装    | 617044 | 603CS6VDE | -  | 6  |
| VDE 绝缘一字螺丝刀 |        | 603VDE    | 0.4 x 2.5x75, 0.8 x 4.0x100,<br>1.0 x 5.5x125, 1.2 x 6.5x150 | 4  |

| 产品名称            | SKU | 文章     | 尺寸              | 数量 |
|-----------------|-----|--------|-----------------|----|
| VDE 绝缘十字(PH)螺丝刀 |     | 613VDE | PH1x80, PH2x100 | 2  |

\* Images of products are symbolic. All dimensions are in mm, and weight in grams. All listed dimensions may vary in tolerance.

### 用途 (pictures)





## Safety tips



• Use a screw holding screwdriver to get screws started in awkward, hard-to-reach areas.

• Use a stubby screwdriver in close quarters where a conventional screwdriver cannot be used.

• A rounded tip should be redressed with a file; make sure edges are straight.

• Screwdrivers used in the shop are best stored in a rack. This way, the proper selection of the right screwdriver can be quickly made.

• Keep the screwdriver handle clean; a greasy handle is apt to cause accidents.

• A screwdriver should never be used as pry bar. If it is overstressed in this manner, the blade might break and send a particle of steel into the operator's arm or even towards his eyes.



• Don't use pliers on the handle of a screwdriver to get extra turning power. A wrench should only be used on the square shank or bolster of a screwdriver that is especially designed for that purpose.

• Don't expose a screwdriver blade to excessive heat as it may reduce the hardness of the blade.

• Don't use a screwdriver with a split or broken handle.

• Don't use a regular screwdriver to check a storage battery or to determine if an electrical circuit is live.

• Don't use tools that shows sign of wear and have the second layer of plastic visible.

• VDE tools that have several parts, have to be assembled correctly before use.

• When working with VDE tools avoid contact with water.