

气动角磨机

1517S



配置文件



产品属性


- 每分钟4500转的空载转速
- 最大气压：6.2 Bar
- 空气消耗量340 升/分钟
- 1/4"进气口
- 5/8"锭子螺纹



优势：

- 小型紧凑工具
- 适合惯用右手或左手人士
- 可拆卸把手
- 易用气动开关

用途：

- 焊件研磨
- 锋利边缘研磨
- 小型不平表面修复



	L	A	D	
617729	375	100	175	2610

* Images of products are symbolic. All dimensions are in mm, and weight in grams. All listed dimensions may vary in tolerance.



用途 (pictures)



Photo (pictures)



Accessories





1/2"气动过滤调节器和润滑器



螺旋气动软管

Safety tips



- The pressure in the tool during the operation has to be at least 6.2 bar for the tool to work properly.
- Regularly clean and dry the air filters and inlet air supply.
- Always use clean and dry air with the correct mixture of oil, for maximum tool life.
- Check the joints and ensure that the tubes and other equipment are not damaged before use.
- All tools should be gently oiled prior to being stored.
- Always store pneumatic tools in dry places away from water.
- Always use original spare parts.
- Repairs can be performed only by authorised staff people authorised by Unior d.d.



- Always disconnect tools not in use from the air supply.