

# 气动角磨机

1518



## 配置文件



## 产品属性

- 每分钟11000转的空载转速
- 最大气压：6.2 Bar
- 空气消耗量170 升/分钟
- 1/4"进气口


## 优势：



- 可拆卸把手
- 防止意外启动的安全杆

## 用途：

- 旋转部件的保护

- 也可用于小空间/面积较小的位置
- 工具行业
- 焊件清洁
- 混凝土和墙壁表面清洁
- 木材表面清洁
- 清除色彩和光泽
- 除锈
- 切割剖面 and 金属板材
- 其他家庭用途



|  | L   | A  | D   |  |
|--|-----|----|-----|---|
| 617730   | 230 | 90 | 125 | 2175  |

\* Images of products are symbolic. All dimensions are in mm, and weight in grams. All listed dimensions may vary in tolerance.

### 用途 (pictures)



### Photo (pictures)




### Accessories




气动管接头



气动管接头



气动管接头



气动管接头



3/8"气动过滤调节器和润滑器



1/2"气动过滤调节器和润滑器



螺旋气动软管

## Safety tips



- The pressure in the tool during the operation has to be at least 6.2 bar for the tool to work properly.
- Regularly clean and dry the air filters and inlet air supply.
- Always use clean and dry air with the correct mixture of oil, for maximum tool life.
- Check the joints and ensure that the tubes and other equipment are not damaged before use.
- All tools should be gently oiled prior to being stored.
- Always store pneumatic tools in dry places away from water.
- Always use original spare parts.
- Repairs can be performed only by authorised staff people authorised by Unior d.d.



- Always disconnect tools not in use from the air supply.