Set i kaçavidave të izoluara VDE TBI me TX profil në kuti kartoni

621CS6VDETBI



Profiles

1000V IEC 60900

Product features

Seti përfshin:


- 6x kaçavidë e izoluar VDE TBI me profil TX (artikulli 621VDETBI) nr. TX10, TX15, TX20, TX25, TX27, TX30

Product name	SKU	Article	Dimensions	Quantity
Set i kaçavidave të izoluara VDE TBI me TX profil në kuti kartoni	617049	621CS6VDETBI	TX 10 - TX 30	6


Product name	SKU	Article	Dimensions	Quantity
Kaçavidë e izoluar VDETBI me TX profil		621VDETBI	TX 10, TX 15, TX 20, TX 25, TX 27, TX 30	6


* Imazhet e produkteve janë simbolike. Të gjitha dimensionet janë në mm, pesha në gram.Të gjitha dimensionet e listuara mund të ndryshojnë në tolerancë.

Usage (pictures)




Ergonomik trajtuar projektimit për mbrojtjen e duart tuaja.






Ergonomik trajtuar dizajn = mbrojtur dorën tuaj



Dora e madhe zona e kontaktit = më shumë pushtet çift rrotullues



Safety tips

- Use a screw holding screwdriver to get screws started in awkward, hard-to-reach areas.
- Use a stubby screwdriver in close quarters where a conventional screwdriver cannot be used.
- A rounded tip should be redressed with a file; make sure edges are straight.
- Screwdrivers used in the shop are best stored in a rack. This way, the proper selection of the right screwdriver can be quickly made.
- Keep the screwdriver handle clean; a greasy handle is apt to cause accidents.
- A screwdriver should never be used as pry bar. If it is overstressed in this manner, the blade

- Don't use pliers on the handle of a screwdriver to get extra turning power. A wrench should only be used on the square shank or bolster of a screwdriver that is especially designed for that purpose.
- Don't expose a screwdriver blade to excessive heat as it may reduce the hardness of the blade.
- Don't use a screwdriver with a split or broken handle.
- Don't use a regular screwdriver to check a storage battery or to determine if an electrical circuit is live.
- Don't use tools that shows sign of wear and have the second layer of plastic visible.

might break and send a particle of steel into the operator's arm or even towards his eyes.

- VDE tools that have several parts, have to be assembled correctly before use.
- When working with VDE tools avoid contact with water.