# Odvijači VDE TBI u garnituri

603CS6VDETBI




## Profili

1000V IEC 60900

## Opis proizvoda

Komplet sadrži:


- 4 kom. izolovanih pljosnatih odvijača sa TBI ručkom (art. 603VDETBI), dim. 0.4x2.5x75, 0.8x4.0x100, 1.0x5.5x125, 1.2x6.5x150
- 2 kom. izolovanih krstastih odvijača (PH) sa TBI ručkom (art. 613VDETBI), dim. PH 1x80, PH 2x100

| Naziv proizvoda | SKU | Artikal | Dimenzije | Količina |
|---|---|---|---|---|
| Odvijači VDE TBI u garnituri | 617042 | 603CS6VDETBI | - | 6 |
| Odvijač VDE TBI pljosnati | | 603VDETBI | 0.4 x 2.5x75, 0.8 x 4.0x100, 1.0 x 5.5x125, 1.2 x 6.5x150 | 4 |


| Naziv proizvoda | SKU | Artikal | Dimenzije | Količina |
|---|---|---|---|---|
| Odvijač VDE TBI krstasti PH |  | 613VDETBI | PH1x80, PH2x100 | 2 |


* Fotografije proizvoda su simbolične. Sve dimenzije su u mm, a težina u gramima. Sve navedene dimenzije mogu odstupati u granicama tolerancija.

## Upotreba (slike)




Ergonomski oblikovana drška za odličan prihvat i zaštitu ruke korisnika






Ergonomski dizajnirana drška štiti vašu ruku



Velika kontaktna površina = veći obrtni moment



# Pravilna upotreba

- Use a screw holding screwdriver to get screws started in awkward, hard-to-reach areas.
- Use a stubby screwdriver in close quarters where a conventional screwdriver cannot be used.
- A rounded tip should be redressed with a file; make sure edges are straight.
- Screwdrivers used in the shop are best stored in a rack. This way, the proper selection of the right screwdriver can be quickly made.
- Keep the screwdriver handle clean; a greasy handle is apt to cause accidents.
- A screwdriver should never be used as pry bar. If it is overstressed in this manner, the blade might break and send a particle of steel into the operator's arm or even towards his eyes.

- Don't use pliers on the handle of a screwdriver to get extra turning power. A wrench should only be used on the square shank or bolster of a screwdriver that is especially designed for that purpose.
- Don't expose a screwdriver blade to excessive heat as it may reduce the hardness of the blade.
- Don't use a screwdriver with a split or broken handle.
- Don't use a regular screwdriver to check a storage battery or to determine if an electrical circuit is live.
- Don't use tools that shows sign of wear and have the second layer of plastic visible.

- VDE tools that have several parts, have to be assembled correctly before use.
- When working with VDE tools avoid contact with water.