带VDE TBI手柄的绝缘套筒扳手套装

629CS6VDETBI

配置文件

产品属性

Set includes:

- 6x insulated socket wrench with VDE TBI handle (article 629VDETBI) dim. 5.5, 6, 7, 8, 10, 13

| 产品名称	SKU	文章	尺寸	数量
带VDE TBI手柄的绝缘套筒扳手套装	617050	629CS6VDETBI	5.5 - 13	6
带VDE TBI手柄的绝缘套筒扳手		629VDETBI	5.5, 6, 7, 8, 10, 13	6

* Images of products are symbolic. All dimensions are in mm, and weight in grams. All listed dimensions may vary in tolerance.

用途 (pictures)

Ergonomic handle design for protecting your hands.

人体工程手柄设计 = 保护手部

较大的手部接触面积 = 更大的转矩功率

Safety tips

- Use a screw holding screwdriver to get screws started in awkward, hard-to-reach areas.

- Use a stubby screwdriver in close quarters where a conventional screwdriver cannot be used.

- A rounded tip should be redressed with a file; make sure edges are straight.

- Screwdrivers used in the shop are best stored in a rack. This way, the proper selection of the right screwdriver can be quickly made.

- Keep the screwdriver handle clean; a greasy handle is apt to cause accidents.

- A screwdriver should never be used as pry bar. If it is overstressed in this manner, the blade might break and send a particle of steel into the operator's arm or even towards his eyes.

- VDE tools that have several parts, have to be assembled correctly before use.

- When working with VDE tools avoid contact with water.

- Don't use pliers on the handle of a screwdriver to get extra turning power. A wrench should only be used on the square shank or bolster of a screwdriver that is especially designed for that purpose.

- Don't expose a screwdriver blade to excessive heat as it may reduce the hardness of the blade.

- Don't use a screwdriver with a split or broken handle.

- Don't use a regular screwdriver to check a storage battery or to determine if an electrical circuit is live.

- Don't use tools that shows sign of wear and have the second layer of plastic visible.