Pro chain wear indicator

1643/4




Profiles

Product features

How to use the tool:

- To alleviate poor shifting and uneven drive train wear, most manufacturers recommend chain replacement at or before 0,6% stretch. Now you can quickly and accurately determine the wear and stretch of any chain. Simply insert the chain checker`s pins into two links, press the swing arm gauge tight, and then check the gauge window for an accurate reading.



		L	B	A			
617170	0 - 1,2	137	25,5	20	119,4	120,6	142

* Images of products are symbolic. All dimensions are in mm, and weight is in grams. All listed dimensions may vary in tolerance.

Usage (pictures)

