# Pneumatikus sarokcsiszoló

1517S



## Profilok

## Termékjellemzők

- üresjárati sebesség: 4500 f/min
- max. üzemi nyomás: 6,2 bar
- levegőfelhasználás: 340 l/min
- levegőcsatlakozás: 1/4"
- tengelycsatlakozás: 5/8"


## Előnyök:

- kisméretű és kompakt szerszám
- bal- és jobbkezesek által egyaránt használható
- eltávolítható markolat
- kézre álló ki-/bekapcsológomb

## Használat:

- hegesztési varratok csiszolása
- éles peremek csiszolása

- kisebb felszíni egyenetlenségek javítása




| | L | A | D | |
|---|---|---|---|---|
| 617729 | 375 | 100 | 175 | 2610 |

* A termékképek illusztrációk. Minden feltüntetett méret milliméterben, a tömegek grammban. Az összes feltüntetett méret eltérhet a toleranciának megfelelően.

## Használat (pictures)



## Photo (pictures)



# Accessories

 Gyorscsatlakozó

 Gyorscsatlakozó

 Gyorscsatlakozó hüvely

 Gyorscsatlakozó hüvely

 Levegőelőkészítő, 3/8"

 Levegőelőkészítő, 1/2"

 Spiráltömlő

## Safety tips

- The pressure in the tool during the operation has to be at least 6.2 bar for the tool to work properly.
- Regularly clean and dry the air filters and inlet air supply.
- Always use clean and dry air with the correct mixture of oil, for maximum tool life.
- Check the joints and ensure that the tubes and other equipment are not damaged before use.
- All tools should be gently oiled prior to being stored.
- Always store pneumatic tools in dry places away from water.
- Always use original spare parts.
- Repairs can be performed only by authorised staff people authorised by Unior d.d.

- Always disconnect tools not in use from the air supply.