钢丝钳

406/1BI



配置文件

标准

ISO 5746

产品属性

- 材料:优质高碳钢
- 落锻，完全淬火与回火
- 切削刃感应淬火
- 头部抛光
- 表面处理：根据ISO 1456:2009标准镀铬
- 重型双成分材料手柄
- UNIOR激光喷码
- 根据ISO 5746标准生产



	L	B	C	A	
607870	160	24	35	9.5	224
607871	180	27	38	10	274
607872	200	29	41	10.5	341
608354	220	32	47	11	421

切割能力 (10N=1kg)

	L	max 1560 N/mm² Ø	max 750 N/mm² Ø
607870	160	1,6	2,0
607871	180	1,8	2,5
607872	200	2,0	2,5
608354	220	2,0	3,0

* Images of products are symbolic. All dimensions are in mm, and weight is in grams. All listed dimensions may vary in tolerance.

用途 (pictures)



Safety tips

- Pliers should be oiled regularly. A drop of oil at the hinge will lengthen the tool life and assure easy operation.

- Don't use pliers for cutting hardened wire, unless specifically manufactured for this purpose.

● When cutting wire with pliers, you should always wear glasses or goggles.

● Handles are provided for comfort. They are not intended to give user any degree of protection against electric shocks and should never be used on live electric circuits.

● Don't expose pliers to excessive heat. This may ruin the tool.

● Don't use pliers as a hammer.

● Don't hammer on the handles. They may crack or break.

● Don't extend the length of plier handles to secure greater leverage.

● Don't use pliers on nuts or bolts. A wrench will do a better job and with less risk of damage to the fastener.

Frequently asked questions

The head profile on the screw has deformed to such an extent that it cannot be unscrewed with a screwdriver. Which Unior tool can be used in this case?
407/4DP screw pliers are the best choice for unscrewing screws with a damaged head profile.