# Комбинирани клешти

406/1BI




## Profiles

## Standards

ИСО 5746

## Product features

- материјал: специјален плус јаглероден челик
- ковани, целосно зајакнати и калени
- ивиците за сечење се индукциски зајакнати
- полирани челусти
- завршна површина: хромирани по стандард EN 12540
- дво-компонентни робусни изолирани рачки
- со втиснат печат УНИОР
- изработени според стандард ISO 5746





| | L | B | C | A | |
|---|---|---|---|---|---|
| 607870 | 160 | 24 | 35 | 9.5 | 224 |
| 607871 | 180 | 27 | 38 | 10 | 274 |
| 607872 | 200 | 29 | 41 | 10.5 | 341 |
| 608354 | 220 | 32 | 47 | 11 | 421 |

Комбинирани клешти капацитет на сечење (10N=1kg)

| | L | max 1560 N/mm² Ø | max 750 N/mm² Ø |
|---|---|---|---|
| 607870 | 160 | 1,6 | 2,0 |
| 607871 | 180 | 1,8 | 2,5 |
| 607872 | 200 | 2,0 | 2,5 |
| 608354 | 220 | 2,0 | 3,0 |

* Сликите на производите се симболични. Сите димензии се во мм, тежината е во грамови. Сите наведени димензии може да се разликуваат во ниво на толеранција

## Usage (pictures)



## Safety tips

● Pliers should be oiled regularly. A drop of oil at the hinge will lengthen the tool life and assure easy operation.

● Don't use pliers for cutting hardened wire, unless specifically manufactured for this purpose.

● When cutting wire with pliers, you should always wear glasses or goggles.

● Handles are provided for comfort. They are not intended to give user any degree of protection against electric shocks and should never be used on live electric circuits.

● Don't expose pliers to excessive heat. This may ruin the tool.

● Don't use pliers as a hammer.

● Don't hammer on the handles. They may crack or break.

● Don't extend the length of plier handles to secure greater leverage.

● Don't use pliers on nuts or bolts. A wrench will do a better job and with less risk of damage to the fastener.

## Frequently asked questions

**The head profile on the screw has deformed to such an extent that it cannot be unscrewed with a screwdriver. Which Unior tool can be used in this case?**
407/4DP screw pliers are the best choice for unscrewing screws with a damaged head profile.