

# 通用铁皮剪

563R/7P



#### 配置文件












## 产品属性

- 材料:特种工具钢
- 落锻,完全淬火与回火
- 刀刃感应淬火
- 防腐蚀保护
- 浸塑料手柄

#### 用途:

以400N/mm²的力剪切最大厚度1.5mm的钣金



	l	C	<b>1</b>
615037	280	47	571

<sup>\*</sup> Images of products are symbolic. All dimensions are in mm, and weight in grams. All listed dimensions may vary in tolerance.

### 用途 (pictures)



## Safety tips



- Be careful of sharp edges on the cutting edges of these tools.
- Use only hand pressure for cutting.
- Snips should be carefully put away after use.
  Wipe the cutting edges with a lightly oiled rag.
- Oil the pivot bolt on the snips occasionally.



- Don't try to cut sharp curves with straight cut snips.
- Don't resharpen a snip blade.
- Don't use snips as a hammer, screwdriver or pry bar. Use proper tools for the job.
- Don't store snips in a drawer with other tools.
  Tools with cutting edges should always be treated with extra respect.
- Never hammer, or use your foot to get extra pressure on the cutting edges.

# Frequently asked questions

#### Can a left-handed person use right-handed cutters?

Yes, the left-handed or right-handed scissors are intended for the direction of the radius cut.