

# Set i bitsa,në kuti plastike

6776PB21



## Profiles






## Product features

- Dimensioni i kuti: 145 x 85 x 40

## Seti përfshin:

- Adapter i bit 1x E6, 3 (1/4") (artikulli 6715E6,3) dim 75
- Bit gjashtëkëndësh 4x (artikulli 6469C6,3) dim. 3, 4, 5, 6
- Bit i profilit TX 9x (artikulli 6472C6,3) dim. TX8, TX9, TX10, TX15, TX20, TX25, TX27, TX30, TX40
- Biit me maje të dyfishtë 3x (PZ) (artikulli 6466C6,3) dim. PZ1, PZ2, PZ3

- Bit i kryqëzuar 2x (PH) (artikulli 6463C6,3) dim. PH1, PH2
- Bit me vrima 2x (artikulli 6460C6,3) dim. 0,5x4,0, 1,2x6,5

Product name	SKU	Article	Dimensions	Quantity
Set i bita,në kuti plastike	621650	6776PB21	-	21
Bit i rrafshët, 3 copë		6460C6,3	0.5 x 4.0, 1.2 x 6.5	2
Bit plus (PZ),3 copë		6466C6,3	PZ 1, PZ 2, PZ 3	3
Bit TX profil,3 copë		6472C6,3	TX 8, TX 9, TX 10, TX 15, TX 20, TX 25, TX 27, TX 30, TX 40	9
Bit imbus,3 copë		6469C6,3	3, 4, 5, 6	4
Bit plus (PH),3 copë		6463C6,3	PH 1, PH 2	2
Mbajtës univerzal me magnet për Bit-sa E6,3 (1/4")		6715E6,3	E6.3 (1/4")x75	1

\* Imazhet e produkteve janë simbolike. Të gjitha dimensionet janë në mm, pesha në gram.Të gjitha dimensionet e listuara mund të ndryshojnë në tolerancë.

## Safety tips



- Use a screw holding screwdriver to get screws started in awkward, hard-to-reach areas.
- Use a stubby screwdriver in close quarters where a conventional screwdriver cannot be used.
- A rounded tip should be redressed with a file; make sure edges are straight.
- Screwdrivers used in the shop are best stored in a rack. This way, the proper selection of the right screwdriver can be quickly made.
- Keep the screwdriver handle clean; a greasy handle is apt to cause accidents.
- A screwdriver should never be used as pry bar. If it is overstressed in this manner, the blade might break and send a particle of steel into the operator's arm or even towards his eyes.



- Don't use pliers on the handle of a screwdriver to get extra turning power. A wrench should only be used on the square shank or bolster of a screwdriver that is especially designed for that purpose.
- Don't expose a screwdriver blade to excessive heat as it may reduce the hardness of the blade.
- Don't use a screwdriver with a split or broken handle.
- Don't use a regular screwdriver to check a storage battery or to determine if an electrical circuit is live.