

Комплет уметоци во пластична касета

6776PB21



Profiles






Product features

- Димензија на касета 145 x 85 x40

Гарнитурата вклучува:

- 1 x Магнетен носач на уметок E 6,3 (1/4") (article 6715E6,3) dim. 75
- 4 x битс уметок имбус (article 6469C6,3) dim. 3, 4, 5, 6
- 9 x Битс уметок со TX профил (article 6472C6,3) dim. TX8, TX9, TX10, TX15, TX20, TX25, TX27, TX30, TX40

- 3 x Двоен битс уметок крстач(PZ) (article 6466C6,3) dim. PZ1, PZ2, PZ3
- 2 x Битс уметок крстач(PH) (article 6463C6,3) dim. PH1, PH2
- 2 x Плоснат битс уметок (article 6460C6,3) dim. 0.5x4.0, 1.2x6.5

Product name	SKU	Article	Dimensions	Quantity
Комплет уметоци во пластична касета	621650	6776PB21	-	21
Плоснат битс уметок, 3 парчиња во гарнитура		6460C6,3	0.5 x 4.0, 1.2 x 6.5	2
Двоен битс уметок крстач(PZ), 3 парчиња во гарнитура		6466C6,3	PZ 1, PZ 2, PZ 3	3
Битс уметок со TX профил, 3 парчиња во гарнитура		6472C6,3	TX 8, TX 9, TX 10, TX 15, TX 20, TX 25, TX 27, TX 30, TX 40	9
Битс уметок имбус, 3 парчиња во гарнитура		6469C6,3	3, 4, 5, 6	4
Битс уметок крстач(PH), 3 парчиња во гарнитура		6463C6,3	PH 1, PH 2	2
Магнетен носач на уметок E 6,3 (1/4")		6715E6,3	E6.3 (1/4")x75	1

* Сликите на производите се симболични. Сите димензии се во мм, тежината е во грамови. Сите наведени димензии може да се разликуваат во ниво на толеранција

Safety tips



- Use a screw holding screwdriver to get screws started in awkward, hard-to-reach areas.
- Use a stubby screwdriver in close quarters where a conventional screwdriver cannot be used.
- A rounded tip should be redressed with a file; make sure edges are straight.
- Screwdrivers used in the shop are best stored in a rack. This way, the proper selection of the right screwdriver can be quickly made.
- Keep the screwdriver handle clean; a greasy handle is apt to cause accidents.
- A screwdriver should never be used as pry bar. If it is overstressed in this manner, the blade



- Don't use pliers on the handle of a screwdriver to get extra turning power. A wrench should only be used on the square shank or bolster of a screwdriver that is especially designed for that purpose.
- Don't expose a screwdriver blade to excessive heat as it may reduce the hardness of the blade.
- Don't use a screwdriver with a split or broken handle.
- Don't use a regular screwdriver to check a storage battery or to determine if an electrical circuit is live.

might break and send a particle of steel into the operator's arm or even towards his eyes.