

# Screwdriver TBI with TX profile

621TBI




## Profiles





## Product features

- blade: premium hard chrome vanadium steel, entirely hardened and tempered
- blade chrome plated, blackened tip
- handle: ergonomic shape
- three component material
- hanging hole




| Barcode | Profile | C   | L   | D   | Weight | Time |
|---------|---------|-----|-----|-----|--------|------|
| 611722  | TX 6    | 60  | 145 | 3   | 34     |      |
| 611724  | TX 8    | 60  | 145 | 3   | 34     |      |
| 611726  | TX 10   | 80  | 165 | 3   | 35     |      |
| 611727  | TX 15   | 80  | 165 | 3,5 | 37     |      |
| 611728  | TX 20   | 100 | 185 | 4   | 43     |      |
| 611729  | TX 25   | 100 | 200 | 4,5 | 63     |      |

|  |  |  |  |  |  |  |
|---|--|--|--|--|--|--|
| 611730  | TX 27  | 115  | 215  | 5.5  | 76   |  |
| 611731  | TX 30  | 115  | 225  | 6  | 98   |  |
| 611732  | TX 40  | 130  | 250  | 7  | 130  |  |

\* Images of products are symbolic. All dimensions are in mm, and weight is in grams. All listed dimensions may vary in tolerance.

## Usage (pictures)



## Safety tips



- Use a screw holding screwdriver to get screws started in awkward, hard-to-reach areas.
- Use a stubby screwdriver in close quarters where a conventional screwdriver cannot be used.
- A rounded tip should be redressed with a file; make sure edges are straight.
- Screwdrivers used in the shop are best stored in a rack. This way, the proper selection of the right screwdriver can be quickly made.
- Keep the screwdriver handle clean; a greasy handle is apt to cause accidents.
- A screwdriver should never be used as pry bar. If it is overstressed in this manner, the blade might break and send a particle of steel into the operator's arm or even towards his eyes.



- Don't use pliers on the handle of a screwdriver to get extra turning power. A wrench should only be used on the square shank or bolster of a screwdriver that is especially designed for that purpose.
- Don't expose a screwdriver blade to excessive heat as it may reduce the hardness of the blade.
- Don't use a screwdriver with a split or broken handle.
- Don't use a regular screwdriver to check a storage battery or to determine if an electrical circuit is live.

## Safety (pictures)

