

Одвртка со ТХ профил ТВ1 изведба

621TBI




Profiles









Product features

- врв од: специјален хард хром ванадиум челик, целосно зајакнат и кален
- стебло на одвртката хромирано, врв појачан
- рачка: ергономска форма
- трикомпонентен материјал
- отвор во рачката за закачување




| Barcode | Profile | C | L | D | Weight |
|---------|---------|----|-----|-----|--------|
| 611722 | TX 6 | 60 | 145 | 3 | 34 |
| 611723 | TX 7 | 60 | 145 | 3 | 34 |
| 611724 | TX 8 | 60 | 145 | 3 | 34 |
| 611725 | TX 9 | 60 | 145 | 3 | 34 |
| 611726 | TX 10 | 80 | 165 | 3 | 35 |
| 611727 | TX 15 | 80 | 165 | 3,5 | 37 |

|  |  |  |  |  |  |
|--|---|---|---|---|---|
| 611728 | TX 20 | 100 | 185 | 4 | 43 |
| 611729 | TX 25 | 100 | 200 | 4.5 | 63 |
| 611730 | TX 27 | 115 | 215 | 5.5 | 76 |
| 611731 | TX 30 | 115 | 225 | 6 | 98 |
| 611732 | TX 40 | 130 | 250 | 7 | 130 |
| 611733 | TX 45 | 130 | 250 | 8 | 148 |

* Сликите на производите се симболични. Сите димензии се во мм, тежината е во грамови. Сите наведени димензии може да се разликуваат во ниво на толеранција

Usage (pictures)



Safety tips



- Use a screw holding screwdriver to get screws started in awkward, hard-to-reach areas.
- Use a stubby screwdriver in close quarters where a conventional screwdriver cannot be used.
- A rounded tip should be redressed with a file; make sure edges are straight.
- Screwdrivers used in the shop are best stored in a rack. This way, the proper selection of the right screwdriver can be quickly made.
- Keep the screwdriver handle clean; a greasy handle is apt to cause accidents.
- A screwdriver should never be used as pry bar. If it is overstressed in this manner, the blade might break and send a particle of steel into the operator's arm or even towards his eyes.



- Don't use pliers on the handle of a screwdriver to get extra turning power. A wrench should only be used on the square shank or bolster of a screwdriver that is especially designed for that purpose.
- Don't expose a screwdriver blade to excessive heat as it may reduce the hardness of the blade.
- Don't use a screwdriver with a split or broken handle.
- Don't use a regular screwdriver to check a storage battery or to determine if an electrical circuit is live.

Safety (pictures)

