

# Tournevis à lames réversibles

### 636A




#### **Profils**



## Description produit

Lames PH2-PH3 et 0, 8x4, 0-1, 2x7, 0



	+	+	axb	axb	L	D	•	
615049	PH 2	PH 3	0.8 x 4.0	1.2 x 7.0	180	7	127	

<sup>\*</sup> Les images des produits ne sont pas contractuelles. Toutes les dimensions sont en mm, les poids en grammes.

# Safety tips





- Use a screw holding screwdriver to get screws started in awkward, hard-to-reach areas.
- Use a stubby screwdriver in close quarters where a conventional screwdriver cannot be
- Don't use pliers on the handle of a screwdriver to get extra turning power. A wrench should only be used on the square shank or bolster of a

used.

- A rounded tip should be redressed with a file; make sure edges are straight.
- Screwdrivers used in the shop are best stored in a rack. This way, the proper selection of the right screwdriver can be quickly made.
- Keep the screwdriver handle clean; a greasy handle is apt to cause accidents.
- A screwdriver should never be used as pry bar. If it is overstressed in this manner, the blade might break and send a particle of steel into the operator's arm or even towards his eyes.

- screwdriver that is especially designed for that purpose.
- Don't expose a screwdriver blade to excessive heat as it may reduce the hardness of the blade.
- Don't use a screwdriver with a split or broken handle.
- Don't use a regular screwdriver to check a storage battery or to determine if an electrical circuit is live.