

# Odvrtlač pneumatski 3/8"

1541



## Profili



## Opis proizvoda

- 10.000 o/min u slobodnom hodu
- max. obrtni moment: 271 Nm
- max. pritisak vazduha: 6, 2 bara
- potrošnja vazduha: 70 l/min
- priključak za vazduh: 1/4"
- za vijke do M10

## Prednosti:


- kontrolisani moment zavrtnanja
- brzo zavrtnanje
- širok spektar upotrebe

## Upotreba:

- auto-industrija
- avio-industrija
- poljoprivredna mehanizacija
- teška industrija
- veće građevinske mašine
- brodogradnja
- individualna montaža

## VAŽNO!

- UVEK koristite Uniorove IMPACT nasadne ključeve i pribor



		<b>L</b>	<b>A</b>	<b>B</b>		
615320	3/8"	139	73,5	175	271	1350

\* Fotografije proizvoda su simbolične. Sve dimenzije su u mm, a težina u gramima. Sve navedene dimenzije mogu odstupati u granicama tolerancija.

## Slika (slike)



## Dodatna oprema



Spojnica muška



Spojnica muška



Spojnica ženska



Spojnica ženska



Priprema grupa za pneumatski alat 3/8"



Priprema grupa za pneumatski alat 1/2"



Crevo spiralno za vazduh

## Pravilna upotreba



- The pressure in the tool during the operation has to be at least 6.2 bar for the tool to work properly.
- Regularly clean and dry the air filters and inlet air supply.
- Always use clean and dry air with the correct mixture of oil, for maximum tool life.
- Check the joints and ensure that the tubes and other equipment are not damaged before use.
- All tools should be gently oiled prior to being stored.
- Always store pneumatic tools in dry places away from water.
- Always use original spare parts.
- Repairs can be performed only by authorised staff people authorised by Unior d.d.



- Always disconnect tools not in use from the air supply.