


# Набор отвёрток для точной механики в картонной упаковке

606CS5E




Профили

---



Описание товара

- 5х отвёрток шлицевых для точной механики (арт. 605E) 0.23 x 1.5х60, 0.3 x 1.8х60, 0.4 x 2.5х75, 0.5 x 3.0х100, 0.8 x 4.0х100

Наименование товара	SKU	Артикул	Размеры	Количество
Набор отвёрток для точной механики в картонной упаковке	620959	606CS5E	-	5
Отвёртка шлицевая для точной механики		605E	0.23 x 1.5х60, 0.3 x 1.8х60, 0.4 x 2.5х75, 0.5 x 3.0х100, 0.8 x 4.0х100	5

\* Изображения продуктов носят демонстрационный характер. Все размеры указаны в миллиметрах, вес в граммах.

### Советы по безопасности



- Use a screw holding screwdriver to get screws started in awkward, hard-to-reach areas.
- Use a stubby screwdriver in close quarters where a conventional screwdriver cannot be used.
- A rounded tip should be redressed with a file; make sure edges are straight.
- Screwdrivers used in the shop are best stored in a rack. This way, the proper selection of the right screwdriver can be quickly made.
- Keep the screwdriver handle clean; a greasy handle is apt to cause accidents.
- A screwdriver should never be used as pry bar. If it is overstressed in this manner, the blade might break and send a particle of steel into the operator's arm or even towards his eyes.



- Don't use pliers on the handle of a screwdriver to get extra turning power. A wrench should only be used on the square shank or bolster of a screwdriver that is especially designed for that purpose.
- Don't expose a screwdriver blade to excessive heat as it may reduce the hardness of the blade.
- Don't use a screwdriver with a split or broken handle.
- Don't use a regular screwdriver to check a storage battery or to determine if an electrical circuit is live.