

# Jeu de tournevis TBI à empreinte TORX

621CS7TBI




## Profils



## Description produit

Le jeu comprend :

- 7 tournevis profil TORX TBI (réf 621TBI) dim TX 10, TX 15, TX 20, TX 25, TX 27, TX 30, TX 40

Nom du produit	SKU	Article	Dimensions	Quantité
Jeu de tournevis TBI à empreinte TORX	612300	621CS7TBI	TX 10 - TX 40	7
Tournevis TBI pour vis à empreinte TORX		621TBI	TX 10, TX 15, TX 20, TX 25, TX 27, TX 30, TX 40	7

\* Les images des produits ne sont pas contractuelles. Toutes les dimensions sont en mm, les poids en grammes.

## Safety tips



- Use a screw holding screwdriver to get screws started in awkward, hard-to-reach areas.
- Use a stubby screwdriver in close quarters where a conventional screwdriver cannot be used.
- A rounded tip should be redressed with a file; make sure edges are straight.
- Screwdrivers used in the shop are best stored in a rack. This way, the proper selection of the right screwdriver can be quickly made.
- Keep the screwdriver handle clean; a greasy handle is apt to cause accidents.
- A screwdriver should never be used as pry bar. If it is overstressed in this manner, the blade might break and send a particle of steel into the operator's arm or even towards his eyes.

- Don't use pliers on the handle of a screwdriver to get extra turning power. A wrench should only be used on the square shank or bolster of a screwdriver that is especially designed for that purpose.
- Don't expose a screwdriver blade to excessive heat as it may reduce the hardness of the blade.
- Don't use a screwdriver with a split or broken handle.
- Don't use a regular screwdriver to check a storage battery or to determine if an electrical circuit is live.

### Safety (pictures)

