

# Jeu de tournevis TBI à empreinte TORX

621CS7TBI




## Profils



## Description produit

Le jeu comprend :

- 7x screwdriver TBI with TX profile (article 621TBI) dim. TX 10, TX 15, TX 20, TX 25, TX 27, TX 30, TX 40

| Nom du produit                          | SKU   | Article   | Dimensions                                      | Quantité |
|---|---|-----------|---|----------|
| Jeu de tournevis TBI à empreinte TORX   | 612300  | 621CS7TBI | TX 10 - TX 40                                   | 7        |
| Tournevis TBI pour vis à empreinte TORX |  | 621TBI    | TX 10, TX 15, TX 20, TX 25, TX 27, TX 30, TX 40 | 7        |

\* Les images des produits ne sont pas contractuelles. Toutes les dimensions sont en mm, les poids en grammes.

# Safety tips



- Use a screw holding screwdriver to get screws started in awkward, hard-to-reach areas.
- Use a stubby screwdriver in close quarters where a conventional screwdriver cannot be used.
- A rounded tip should be redressed with a file; make sure edges are straight.
- Screwdrivers used in the shop are best stored in a rack. This way, the proper selection of the right screwdriver can be quickly made.
- Keep the screwdriver handle clean; a greasy handle is apt to cause accidents.
- A screwdriver should never be used as pry bar. If it is overstressed in this manner, the blade might break and send a particle of steel into the operator's arm or even towards his eyes.



- Don't use pliers on the handle of a screwdriver to get extra turning power. A wrench should only be used on the square shank or bolster of a screwdriver that is especially designed for that purpose.
- Don't expose a screwdriver blade to excessive heat as it may reduce the hardness of the blade.
- Don't use a screwdriver with a split or broken handle.
- Don't use a regular screwdriver to check a storage battery or to determine if an electrical circuit is live.

## Safety (pictures)

