

# Набор отвёрток с профилем TORX с центральным отверстием, рукоятки TBI, в картонной упаковке

621/1CS7TBI



## Профили




## Описание товара

### В комплекте:

- 7х отвёрток с профилем TORX с центральным отверстием, рукоятка TBI (арт. 621/1TBI) TR 10, TR 15, TR 20, TR 25, TR 27, TR 30, TR 40

Наименование товара	SKU	Артикул	Размеры	Количество
Набор отвёрток с профилем TORX с центральным отверстием, рукоятки TBI, в картонной упаковке	612308	621/1CS7TBI	TR 10 - TR 40	7

Наименование товара	SKU	Артикул	Размеры	Количество
Отвёртка с профилем TORX с центральным отверстием, рукоятка TBI		621/1TBI	TR 10, TR 15, TR 20, TR 25, TR 27, TR 30, TR 40	7

\* Изображения продуктов носят демонстрационный характер. Все размеры указаны в миллиметрах, вес в граммах.

## Советы по безопасности



- Use a screw holding screwdriver to get screws started in awkward, hard-to-reach areas.
- Use a stubby screwdriver in close quarters where a conventional screwdriver cannot be used.
- A rounded tip should be redressed with a file; make sure edges are straight.
- Screwdrivers used in the shop are best stored in a rack. This way, the proper selection of the right screwdriver can be quickly made.
- Keep the screwdriver handle clean; a greasy handle is apt to cause accidents.
- A screwdriver should never be used as pry bar. If it is overstressed in this manner, the blade might break and send a particle of steel into the operator's arm or even towards his eyes.



- Don't use pliers on the handle of a screwdriver to get extra turning power. A wrench should only be used on the square shank or bolster of a screwdriver that is especially designed for that purpose.
- Don't expose a screwdriver blade to excessive heat as it may reduce the hardness of the blade.
- Don't use a screwdriver with a split or broken handle.
- Don't use a regular screwdriver to check a storage battery or to determine if an electrical circuit is live.

### Безопасность (картинки)

