

# 锻造棘轮梅花扳手

170/2



## 配置文件




## 产品属性





- 材料：铬钒钢
- 落锻，完全淬火与回火

## 优势：

- 棘轮：两个方向均可，可通过按钮更换
- 72 - 齿，5°工作角度
- 扳手棘轮部分上的止动环可防止扳手在螺母上意外滑落
- 可以方便快捷的紧固螺母，且不会对用户造成损失，同时还可以实现使扳手快速准确定位。



Barcode	mm	L	B2	B1	A2	A1	Icon	Icon
622851	6 x 8	114,2	17,4	17,4	8,4	8,4	40	Till end of stock
622852	8 x 9	130,4	20,9	17,4	8,4	8,4	55	Till end of stock
622853	8 x 10	130,4	20,9	17,4	8,4	8,4	55	Till end of stock

		L	B2	B1	A2	A1		
622854	10 x 11	144,4	22,9	20,9	9,7	8,4	72	Till end of stock
622856	12 x 13	166	24,9	23,4	9,7	9,7	97	Till end of stock
622857	14 x 15	181,4	30,4	27,4	11,7	10,1	142	Till end of stock
622858	16 x 18	205,9	33,9	30,4	12	11,7	198	Till end of stock
622859	17 x 19	224,4	34,4	31,9	12	11,7	211	Till end of stock

\* Images of products are symbolic. All dimensions are in mm, and weight in grams. All listed dimensions may vary in tolerance.

## Frequently asked questions

### **Do wrenches with a ratchet need to be oiled?**

No, the ratchet mechanism should not be oiled, but the dirt should be removed with a non-corrosive cleaning agent.