

# CR柄电工十字螺丝刀

#### 612CR




配置文件



产品属性

- 螺丝刀:切割器-特种工具钢、锻造、完全淬火与回火,完全淬火与回火
- 镀铬刀片,黑色刀头
- 手柄:符合人体工程学的形状
- 手柄:聚丙烯
- 挂孔
- 根据DIN5260-PH标准制造



	+	C	L	D	<b>1</b>
616361	PH 2	200	300	6	98
616362	PH 2	280	380	6	113

\* Images of products are symbolic. All dimensions are in mm, and weight in grams. All listed dimensions may vary in tolerance.

## Safety tips



• Use a screw holding screwdriver to get screws started in awkward, hard-to-reach areas.

• Use a stubby screwdriver in close quarters where a conventional screwdriver cannot be used.

• A rounded tip should be redressed with a file; make sure edges are straight.

• Screwdrivers used in the shop are best stored in a rack. This way, the proper selection of the right screwdriver can be quickly made.

• Keep the screwdriver handle clean; a greasy handle is apt to cause accidents.


• A screwdriver should never be used as pry bar. If it is overstressed in this manner, the blade might break and send a particle of steel into the operator's arm or even towards his eyes. • Don't use pliers on the handle of a screwdriver to get extra turning power. A wrench should only be used on the square shank or bolster of a screwdriver that is especially designed for that purpose.

• Don't expose a screwdriver blade to excessive heat as it may reduce the hardness of the blade.

• Don't use a screwdriver with a split or broken handle.

• Don't use a regular screwdriver to check a storage battery or to determine if an electrical circuit is live.

#### Safety (pictures)



### Frequently asked questions

#### Can you hit the screwdriver?

No, you should not hit the screwdriver.

#### Can a screwdriver with a PH tip be used for PZ cross head screws?

Its use is not recommended as this can cause damage to the screw.