

# Schroevendraaier, CR TX

621CR




## Profielen



## Product attributen

- blade: premium hard chrome vanadium steel, entirely hardened and tempered
- blade chrome plated, blackened tip
- handle: ergonomic shape
- handle - polypropylene
- hanging hole



| Barcode | Star  | C  | L   | D   | Icon | Icon              |
|---------|-------|----|-----|-----|------|-------------------|
| 616379  | TX 6  | 60 | 145 | 3   | 34   |                   |
| 616380  | TX 7  | 80 | 165 | 3   | 34   | Till end of stock |
| 616381  | TX 8  | 80 | 165 | 3   | 34   |                   |
| 616382  | TX 9  | 80 | 165 | 3   | 34   |                   |
| 616383  | TX 10 | 80 | 165 | 3   | 35   |                   |
| 616384  | TX 15 | 80 | 165 | 3.5 | 37   |                   |

|        |       | C   | L   | D   |     |
|--------|-------|-----|-----|-----|-----|
| 616385 | TX 20 | 100 | 185 | 4   | 43  |
| 616386 | TX 25 | 100 | 185 | 4.5 | 63  |
| 616387 | TX 27 | 115 | 215 | 5.5 | 76  |
| 616388 | TX 30 | 115 | 215 | 6   | 98  |
| 616389 | TX 40 | 130 | 240 | 7   | 130 |

\* Afbeeldingen van producten zijn symbolisch. Alle afmetingen zijn in mm en gewicht in gram. Alle vermelde afmetingen kunnen variëren in tolerantie.

## Veiligheidstips



- Use a screw holding screwdriver to get screws started in awkward, hard-to-reach areas.
- Use a stubby screwdriver in close quarters where a conventional screwdriver cannot be used.
- A rounded tip should be redressed with a file; make sure edges are straight.
- Screwdrivers used in the shop are best stored in a rack. This way, the proper selection of the right screwdriver can be quickly made.
- Keep the screwdriver handle clean; a greasy handle is apt to cause accidents.
- A screwdriver should never be used as pry bar. If it is overstressed in this manner, the blade might break and send a particle of steel into the operator's arm or even towards his eyes.



- Don't use pliers on the handle of a screwdriver to get extra turning power. A wrench should only be used on the square shank or bolster of a screwdriver that is especially designed for that purpose.
- Don't expose a screwdriver blade to excessive heat as it may reduce the hardness of the blade.
- Don't use a screwdriver with a split or broken handle.
- Don't use a regular screwdriver to check a storage battery or to determine if an electrical circuit is live.

## Veiligheid (Afbeeldingen)

