


# Çelës i thethësisë me dorez CR

629CR





## Profiles



## Product features

- teh: çeliku krom-molibden vanadium-, thekur tërësisht dhe nevrík
- krom kromuar the
- trajtuar: formë ergonomik
- trajtuar - polipropilen
- varur vrimë
- bërë sipas standardit DIN 3125



|  |  | C   | L   | D   |  |
|--|---|-----|-----|-----|---|
| 616404   | 4   | 125 | 225 | 5   | 73  |
| 616406   | 5   | 125 | 225 | 5,2 | 92  |
| 616407   | 5.5   | 125 | 225 | 5,2 | 103   |
| 616408   | 6   | 125 | 225 | 5,2 | 103   |
| 616409   | 7   | 125 | 235 | 6,2 | 123   |

|  |  | C   | L   | D   |  |
|--|---|-----|-----|-----|---|
| 616410   | 8   | 125 | 235 | 6,2 | 140   |
| 616411   | 10  | 125 | 235 | 8,2 | 157   |
| 616413   | 12  | 125 | 245 | 9,2 | 184   |
| 616414   | 13  | 125 | 245 | 9,2 | 186   |
| 616415   | 14  | 125 | 245 | 9   | 193   |
| 616418   | 17  | 125 | 245 | 9   | 210   |

\* Imazhet e produkteve janë simbolike. Të gjitha dimensionet janë në mm, pesha në gram. Të gjitha dimensionet e listuara mund të ndryshojnë në tolerancë.

## Safety tips



- Use a screw holding screwdriver to get screws started in awkward, hard-to-reach areas.
- Use a stubby screwdriver in close quarters where a conventional screwdriver cannot be used.
- A rounded tip should be redressed with a file; make sure edges are straight.
- Screwdrivers used in the shop are best stored in a rack. This way, the proper selection of the right screwdriver can be quickly made.
- Keep the screwdriver handle clean; a greasy handle is apt to cause accidents.
- A screwdriver should never be used as pry bar. If it is overstressed in this manner, the blade might break and send a particle of steel into the operator's arm or even towards his eyes.



- Don't use pliers on the handle of a screwdriver to get extra turning power. A wrench should only be used on the square shank or bolster of a screwdriver that is especially designed for that purpose.
- Don't expose a screwdriver blade to excessive heat as it may reduce the hardness of the blade.
- Don't use a screwdriver with a split or broken handle.
- Don't use a regular screwdriver to check a storage battery or to determine if an electrical circuit is live.