

# Izvijač plosnati NI

605NI



## Profili




## Zatvori pretraživanje




DIN 5265, ISO 2380-1, 2

## Atributi proizvoda

- oštrica od Premium Hard krom-vanadijev čelika, u cjelosti ojačana i zakaljena
- tijelo niklovano
- ručka ergonomski oblikovana
- ručica od polipropilena
- otvor u dršci za vješanje
- izrađeno prema standardu ISO2380-1,2



|  | axb       | C  | L   | D   |  |  |
|--|-----------|----|-----|-----|---|---|
| 616419   | 0.4 x 2.0 | 60 | 145 | 2   | 33  |   |
| 616420   | 0.4 x 2.5 | 75 | 160 | 2.5 | 34  | Till end of stock   |

|  | axb        | C   | L   | D   |  |  |
|--|------------|-----|-----|-----|---|---|
| 616421   | 0.5 x 3.0  | 80  | 165 | 3   | 35  |   |
| 616422   | 0.6 x 3.5  | 100 | 185 | 3.5 | 39  | Till end of stock   |
| 616423   | 0.8 x 4.0  | 100 | 185 | 4   | 41  |   |
| 616424   | 1.0 x 5.5  | 125 | 225 | 5   | 70  |   |
| 616425   | 1.2 x 6.5  | 150 | 250 | 6   | 103   |   |
| 616426   | 1.2 x 8.0  | 175 | 285 | 7   | 143   |   |
| 616427   | 1.6 x 10.0 | 200 | 320 | 8   | 173   |   |

\* Slike proizvoda su simbolične. Sve dimenzije su u mm, masa je u g.

## Safety tips



- Use a screw holding screwdriver to get screws started in awkward, hard-to-reach areas.
- Use a stubby screwdriver in close quarters where a conventional screwdriver cannot be used.
- A rounded tip should be redressed with a file; make sure edges are straight.
- Screwdrivers used in the shop are best stored in a rack. This way, the proper selection of the right screwdriver can be quickly made.
- Keep the screwdriver handle clean; a greasy handle is apt to cause accidents.
- A screwdriver should never be used as pry bar. If it is overstressed in this manner, the blade might break and send a particle of steel into the operator's arm or even towards his eyes.



- Don't use pliers on the handle of a screwdriver to get extra turning power. A wrench should only be used on the square shank or bolster of a screwdriver that is especially designed for that purpose.
- Don't expose a screwdriver blade to excessive heat as it may reduce the hardness of the blade.
- Don't use a screwdriver with a split or broken handle.
- Don't use a regular screwdriver to check a storage battery or to determine if an electrical circuit is live.

## Safety (pictures)

