

# Surbelnita hexagonala CR

### 620/1CR




#### Profile



#### Caracteristicile produsului

- lama:otel crom vanadium molibden tratata integral
- lama brunata
- maner:forma ergonomica
- maner-polipropilena
- gaura de agatare





\* Imaginea produsului este simbolica. Toate dimensiunile sunt exprimate în mm, greutatea în grame.

## Safety tips



• Use a screw holding screwdriver to get screws started in awkward, hard-to-reach areas.



• Don't use pliers on the handle of a screwdriver to get extra turning power. A wrench should only be

• Use a stubby screwdriver in close quarters where a conventional screwdriver cannot be used.

• A rounded tip should be redressed with a file; make sure edges are straight.

• Screwdrivers used in the shop are best stored in a rack. This way, the proper selection of the right screwdriver can be quickly made.

• Keep the screwdriver handle clean; a greasy handle is apt to cause accidents.

• A screwdriver should never be used as pry bar. If it is overstressed in this manner, the blade might break and send a particle of steel into the operator's arm or even towards his eyes. used on the square shank or bolster of a screwdriver that is especially designed for that purpose.

• Don't expose a screwdriver blade to excessive heat as it may reduce the hardness of the blade.

• Don't use a screwdriver with a split or broken handle.

• Don't use a regular screwdriver to check a storage battery or to determine if an electrical circuit is live.

#### Safety (pictures)

