

Set kaçavidash CR,në kuti kartoni

609CS7CR





Profiles



Product features

Seti përfshin:

- Kaçavidë e rrafshhtë CR 4x (artikull 605CR) zbehtë. 0,8x4,0x100, 1,0x5,5x125, 1,2x6,5x150, 1,2x8,0x175
- Kaçavidë 3x me majë plus (PZ) CR (artikulli 625CR) dim. PZ 1x80, PZ 2x100, PZ 3x150

Product name	SKU	Article	Dimensions	Quantity
Set kaçavidash CR,në kuti kartoni	617030	609CS7CR	-	7
Kaçavidë e rrafshhtë CR		605CR	0.8 x 4.0x100, 1.0 x 5.5x125, 1.2 x 6.5x150, 1.2 x 8.0x175	4
Kaçavidë plus (PZ) CR		625CR	PZ 1x80, PZ 2x100, PZ 3x150	3

* Imazhet e produkteve janë simbolike. Të gjitha dimensionet janë në mm, pesha në gram. Të gjitha dimensionet e listuara mund të ndryshojnë në tolerancë.

Safety tips



- Use a screw holding screwdriver to get screws started in awkward, hard-to-reach areas.
- Use a stubby screwdriver in close quarters where a conventional screwdriver cannot be used.
- A rounded tip should be redressed with a file; make sure edges are straight.
- Screwdrivers used in the shop are best stored in a rack. This way, the proper selection of the right screwdriver can be quickly made.
- Keep the screwdriver handle clean; a greasy handle is apt to cause accidents.
- A screwdriver should never be used as pry bar. If it is overstressed in this manner, the blade might break and send a particle of steel into the operator's arm or even towards his eyes.



- Don't use pliers on the handle of a screwdriver to get extra turning power. A wrench should only be used on the square shank or bolster of a screwdriver that is especially designed for that purpose.
- Don't expose a screwdriver blade to excessive heat as it may reduce the hardness of the blade.
- Don't use a screwdriver with a split or broken handle.
- Don't use a regular screwdriver to check a storage battery or to determine if an electrical circuit is live.

Safety (pictures)

