

# Zestaw wkrętekó NI

607B5NI





## Profile



## Cechy produktu

### Zestaw zawiera:

- 3x wkrętek płaski (art. 605NI) rozm. 0.5x3.0x80, 0.8x4.0x100, 1.2x6.5x150
- 2x wkrętek krzyżakowy (PH) NI (art. 615NI) rozm. PH 1x80, PH 2x100

| Nazwa produktu          | SKU   | Artykuł | Wymiary                                       | Ilość |
|-------------------------|---|---------|---|-------|
| Zestaw wkrętekó NI      | 617037  | 607B5NI | -   | 5     |
| Wkrętek płaski          |  | 605NI   | 0.5 x 3.0x80, 0.8 x 4.0x100,<br>1.2 x 6.5x150 | 3     |
| Wkrętek krzyżakowy (PH) |  | 615NI   | PH 1x80, PH 2x100                             | 2     |

\* Przedstawiony wygląd produktu jest orientacyjny. Wszystkie wymiary są w mm, podana waga w gramach

# Wskazówki bezpieczeństwa



- Use a screw holding screwdriver to get screws started in awkward, hard-to-reach areas.
- Use a stubby screwdriver in close quarters where a conventional screwdriver cannot be used.
- A rounded tip should be redressed with a file; make sure edges are straight.
- Screwdrivers used in the shop are best stored in a rack. This way, the proper selection of the right screwdriver can be quickly made.
- Keep the screwdriver handle clean; a greasy handle is apt to cause accidents.
- A screwdriver should never be used as pry bar. If it is overstressed in this manner, the blade might break and send a particle of steel into the operator's arm or even towards his eyes.



- Don't use pliers on the handle of a screwdriver to get extra turning power. A wrench should only be used on the square shank or bolster of a screwdriver that is especially designed for that purpose.
- Don't expose a screwdriver blade to excessive heat as it may reduce the hardness of the blade.
- Don't use a screwdriver with a split or broken handle.
- Don't use a regular screwdriver to check a storage battery or to determine if an electrical circuit is live.

## Bezpieczeństwo (Obrazy)

