

Szigetelt csavarhúzó-készlet VDE TBI markolattal, fáziskeresővel

603CS6TVDETBI



Profilok



Termékjellemzők

Készlet tartalma:


- 3x villanyszerelő csavarhúzó szigetelt szárral, VDE TBI (603VDETBI): 0.8x4.0x100, 1.0x5.5x125, 1.2x6.5x150
- 2x Phillips csavarhúzó szigetelt szárral, VDE TBI (613VDETBI): PH 1x80, PH 2x100
- 1x fáziskereső 220 - 250 V (630VDE): 0.5x3.0x140

| Termék megnevezése | SKU | Cikk | Méretek | Mennyiség |
|---|--------|---------------|---------|-----------|
| Szigetelt csavarhúzó-készlet VDE TBI markolattal, fáziskeresővel | 617043 | 603CS6TVDETBI | - | 6 |



| Termék megnevezése | SKU | Cikk | Méretek | Mennyiség |
|--|-----|-----------|---|-----------|
| Szigetelt lapos (SL) villanyszerelő csavarhúzó VDE TBI markolattal | | 603VDETBI | 0.8 x 4.0x100, 1.0 x 5.5x125, 1.2 x 6.5x150 | 3 |
| Szigetelt Phillips (PH) csavarhúzó VDE TBI markolattal | | 613VDETBI | PH1x80, PH2x100 | 2 |
| Fáziskereső, 220 - 250 V | | 630VDE | 0.5 x 3.0x140 | 1 |

* A termékképek illusztrációk. minden feltüntetett méret milliméterben, a tömegek grammban. Az összes feltüntetett méret eltérhet a toleranciának megfelelően.


Használat (pictures)




Ergonomikus markolatkialakítás a kezek védelméért.



Ergonómiaileg tervezett markolat = a kéz védelme



Nagyobb érintkező felület a kézzel = nagyobb nyomaték



Safety tips



- Use a screw holding screwdriver to get screws started in awkward, hard-to-reach areas.
- Use a stubby screwdriver in close quarters where a conventional screwdriver cannot be used.
- A rounded tip should be redressed with a file; make sure edges are straight.
- Screwdrivers used in the shop are best stored in a rack. This way, the proper selection of the right screwdriver can be quickly made.



- Don't use pliers on the handle of a screwdriver to get extra turning power. A wrench should only be used on the square shank or bolster of a screwdriver that is especially designed for that purpose.
- Don't expose a screwdriver blade to excessive heat as it may reduce the hardness of the blade.
- Don't use a screwdriver with a split or broken handle.
- Don't use a regular screwdriver to check a storage battery or to determine if an electrical circuit is live.

- Keep the screwdriver handle clean; a greasy handle is apt to cause accidents.
- A screwdriver should never be used as pry bar. If it is overstressed in this manner, the blade might break and send a particle of steel into the operator's arm or even towards his eyes.
- VDE tools that have several parts, have to be assembled correctly before use.
- When working with VDE tools avoid contact with water.
- Don't use tools that shows sign of wear and have the second layer of plastic visible.