

Гарнитура одвртувачи VDE TBI со тестер на волтажа

603CS6TVDEETBI




Profiles





Product features

Гарнитурата вклучува:


- 4 x електричарски плоснат одвртувач VDEETBI (article 603VDEETBI) dim. 0.8x4.0x100, 1.0x5.5x125, 1.2x6.5x150
- 2 x одвртка крстач изолиран , VDE TBI изведба (613VDEETBI) dim. PH 1x80, PH 2x100
- 1x тестер за напон 220-250V (article 630VDE) dim. 0.5x3.0x140

| Product name | SKU | Article | Dimensions | Quantity |
|--|---|----------------|--|----------|
| Гарнитура одвртувачи VDE TBI со тестер на волтажа | 617043 | 603CS6TVDEETBI | - | 6 |
| Одвртка изолирана плосната за Електричари , VDE TBI изведба |  | 603VDEETBI | 0.8 x 4.0x100, 1.0 x 5.5x125, 1.2 x 6.5x150 | 3 |



| Product name | SKU | Article | Dimensions | Quantity |
|--|---|------------|-----------------|----------|
| Одвртка крстач (PH) изолиран, VDE TBI изведба |  | 613VDE TBI | PH1x80, PH2x100 | 2 |
| Тестер на напон 220 -250 |  | 630VDE | 0.5 x 3.0x140 | 1 |

* Сликите на производите се симболични. Сите димензии се во мм, тежината е во грамови. Сите наведени димензии може да се разликуваат во ниво на толеранција


Usage (pictures)




Ергономската рачка е изработена за заштита на вашите дланки.



Ергономски дизајн на рачката = ја заштитува вашата дланка



Голема контакт област на дланката=повеќе сила на момент на вртежи



Safety tips



- Use a screw holding screwdriver to get screws started in awkward, hard-to-reach areas.
- Use a stubby screwdriver in close quarters where a conventional screwdriver cannot be used.
- A rounded tip should be redressed with a file; make sure edges are straight.
- Screwdrivers used in the shop are best stored in a rack. This way, the proper selection of the right screwdriver can be quickly made.
- Keep the screwdriver handle clean; a greasy handle is apt to cause accidents.



- Don't use pliers on the handle of a screwdriver to get extra turning power. A wrench should only be used on the square shank or bolster of a screwdriver that is especially designed for that purpose.
- Don't expose a screwdriver blade to excessive heat as it may reduce the hardness of the blade.
- Don't use a screwdriver with a split or broken handle.
- Don't use a regular screwdriver to check a storage battery or to determine if an electrical circuit is live.
- Don't use tools that shows sign of wear and have the second layer of plastic visible.

- A screwdriver should never be used as pry bar. If it is overstressed in this manner, the blade might break and send a particle of steel into the operator's arm or even towards his eyes.
- VDE tools that have several parts, have to be assembled correctly before use.
- When working with VDE tools avoid contact with water.