

# Chain wear indicator

1644/4



## Profiles



## Product features


- Made from precision, laser cut steel.

## How to use the tool:

- A worn chain shifts poorly and causes undue damage to the sprockets. The tool is a "go, no go" gauge designed to accurately indicate when a chain is worn out.

## Important!

- Measurement: from 0 to 0,6% - no chain wear. from 0,7 to 1,2% the chain is worn out and it is necessary to replace it.



617171

L

122,5

A

2

B

37

C

12,7



40

\* Images of products are symbolic. All dimensions are in mm, and weight in grams. All listed dimensions may vary in tolerance.

## Usage (pictures)

