

气动磨砂机

1510



配置文件



产品属性

- 每分钟10000转的空载转速
- 最大气压：6.2 Bar
- 空气消耗量212 升/分钟
- 1/4"进气口
- 尼龙磨砂垫


优势：

- 把手的人体工程形状可实现良好的握持并防止滑动。
- 适合惯用右手或左手人士
- 安静有力的驱动
- 易用开关
- 将废弃物放入袋中，使工作场所保持整洁
- 灵活耐用的软管用于清洁灰尘

- 不可远离操作平台边缘
- 将震动减至最少以优化工作条件
- 此重量产生的极限功率(1.2 kg)

用途:

- 汽车车间
- 不同工作台的准备工作，以进行后续工艺
- 适合研磨结构钢、金属和木材
- 磨砂机VELCRO™可快速、简单安全的安装和拆卸各种磨砂片.此系统适用于各种情况 - 已知最好的例子是带有VELCRO™紧固的训练鞋。



	Nº	L	A	D	
617713	5	220	105	150	1615

* Images of products are symbolic. All dimensions are in mm, and weight is in grams. All listed dimensions may vary in tolerance.

用途 (pictures)




Photo (pictures)



Accessories



气动管接头



气动管接头



气动管接头



气动管接头



3/8"气动过滤调节器和润滑器



1/2"气动过滤调节器和润滑器



螺旋气动软管

Safety tips



- The pressure in the tool during the operation has to be at least 6.2 bar for the tool to work properly.
- Regularly clean and dry the air filters and inlet air supply.
- Always use clean and dry air with the correct mixture of oil, for maximum tool life.
- Check the joints and ensure that the tubes and other equipment are not damaged before use.
- All tools should be gently oiled prior to being stored.
- Always store pneumatic tools in dry places away from water.
- Always use original spare parts.
- Repairs can be performed only by authorised staff people authorised by Unior d.d.



- Always disconnect tools not in use from the air supply.