

# Pneumatikus sarokcsiszoló

1517S



## Profilok



## Termékjellemzők


- üresjárat sebesség: 4500 f/min
- max. üzemi nyomás: 6,2 bar
- levegőfelhasználás: 340 l/min
- levegőcsatlakozás: 1/4"
- tengelycsatlakozás: 5/8"

## Előnyök:

- kisméretű és kompakt szerszám
- bal- és jobbkezesek által egyaránt használható
- eltávolítható markolat
- kézre álló ki-/bekapcsológomb

## Használat:

- hegesztési varratok csiszolása
- éles peremek csiszolása
- kisebb felszíni egyenetlenségek javítása



617729

L

375

A

100

D

175



2610

\* A termékeképek illusztrációk. Minden feltüntetett méret milliméterben, a tömegek grammban. Az összes feltüntetett méret eltérhet a toleranciának megfelelően.

## Használat (pictures)



## Photo (pictures)



## Accessories



Gyorscsatlakozó



Gyorscsatlakozó



Gyorscsatlakozó hüvely



Gyorscsatlakozó hüvely



Levegőelőkészítő, 3/8"



Levegőelőkészítő, 1/2"



Spiráltömlő

## Safety tips



- The pressure in the tool during the operation has to be at least 6.2 bar for the tool to work properly.
- Regularly clean and dry the air filters and inlet air supply.
- Always use clean and dry air with the correct mixture of oil, for maximum tool life.
- Check the joints and ensure that the tubes and other equipment are not damaged before use.
- All tools should be gently oiled prior to being stored.
- Always store pneumatic tools in dry places away from water.
- Always use original spare parts.
- Repairs can be performed only by authorised staff people authorised by Unior d.d.



- Always disconnect tools not in use from the air supply.