

Brusilica ugaona pneumatska

1517S



Profili



Opis proizvoda


- broj obrtaja u slobodnom hodu: 4500/min
- max. pritisak vazduha: 6, 2 bara
- potrošnja vazduha: 340 l/min
- priključak za vazduh: 1/4"
- navoj glave: 5/8"

Prednosti:

- mali i kompaktni alat
- pogodno i za levoruke i za one koji rade desnom rukom
- zamenljiva drška
- pogodno pozicioniran prekidač

Upotreba:

- brušenje varova
- brušenje oštih ivica
- za manje neravne površine



L

A

D



617729

375

100

175

2610

* Fotografije proizvoda su simbolične. Sve dimenzije su u mm, a težina u gramima. Sve navedene dimenzije mogu odstupati u granicama tolerancija.

Upotreba (slike)



Slika (slike)



Dodatna oprema




Spojnica muška



Spojnica muška



Spojnica ženska



Spojnica ženska



Priprema grupa za pneumatski alat 3/8"



Pripremna grupa za pneumatski alat 1/2"



Crevo spiralno za vazduh

Pravilna upotreba



- The pressure in the tool during the operation has to be at least 6.2 bar for the tool to work properly.
- Regularly clean and dry the air filters and inlet air supply.
- Always use clean and dry air with the correct mixture of oil, for maximum tool life.
- Check the joints and ensure that the tubes and other equipment are not damaged before use.
- All tools should be gently oiled prior to being stored.
- Always store pneumatic tools in dry places away from water.
- Always use original spare parts.
- Repairs can be performed only by authorised staff people authorised by Unior d.d.



- Always disconnect tools not in use from the air supply.