

气动角磨机

1518



配置文件



产品属性

- 每分钟11000转的空载转速
- 最大气压：6.2 Bar
- 空气消耗量170 升/分钟
- 1/4"进气口


优势：

- 可拆卸把手
- 防止意外启动的安全杆

用途：

- 旋转部件的保护

- 也可用于小空间/面积较小的位置
- 工具行业
- 焊件清洁
- 混凝土和墙壁表面清洁
- 木材表面清洁
- 清除色彩和光泽
- 除锈
- 切割剖面 and 金属板材
- 其他家庭用途



617730	L	A	D	2175
617730	230	90	125	2175

* Images of products are symbolic. All dimensions are in mm, and weight is in grams. All listed dimensions may vary in tolerance.

用途 (pictures)



Photo (pictures)




Accessories




气动管接头



气动管接头



气动管接头



气动管接头



3/8"气动过滤调节器和润滑器



1/2"气动过滤调节器和润滑器



螺旋气动软管

Safety tips



- The pressure in the tool during the operation has to be at least 6.2 bar for the tool to work properly.
- Regularly clean and dry the air filters and inlet air supply.
- Always use clean and dry air with the correct mixture of oil, for maximum tool life.
- Check the joints and ensure that the tubes and other equipment are not damaged before use.
- All tools should be gently oiled prior to being stored.
- Always store pneumatic tools in dry places away from water.
- Always use original spare parts.
- Repairs can be performed only by authorised staff people authorised by Unior d.d.



- Always disconnect tools not in use from the air supply.