

# Brusilica pneumatska

1518



## Profilii



## Opis proizvoda

- broj obrtaja u slobodnom hodu: 11000/min
- max. pritisak vazduha: 6, 2 bara
- potrošnja vazduha: 170 l/min
- priključak za vazduh: 1/4"


## Prednosti:

- zamenljiva drška
- sigurnosna ručica onemogućava neželjena uključivanja alata

## Upotreba:

- zaštita od rotirajućih delova

- može se upotrebljavati u manjem prostoru
- industrija alata
- čišćenje varova
- čišćenje betonskih površina i zidova
- čišćenje drvenih površina
- odstranjivanje boja i lakova
- odstranjivanje rđe
- sečenje profilnih nosača i lima
- druga kućna upotreba



	L	A	D	
617730	230	90	125	2175

\* Fotografije proizvoda su simbolične. Sve dimenzije su u mm, a težina u gramima. Sve navedene dimenzije mogu odstupati u granicama tolerancija.

### Upotreba (slike)



### Slika (slike)



### Dodatna oprema



Spojnica muška



Spojnica muška



Spojnica ženska



Spojnica ženska



Pripremna grupa za pneumatski alat 3/8"



Pripremna grupa za pneumatski alat 1/2"



Crevo spiralno za vazduh

## Pravilna upotreba



- The pressure in the tool during the operation has to be at least 6.2 bar for the tool to work properly.
- Regularly clean and dry the air filters and inlet air supply.
- Always use clean and dry air with the correct mixture of oil, for maximum tool life.
- Check the joints and ensure that the tubes and other equipment are not damaged before use.
- All tools should be gently oiled prior to being stored.
- Always store pneumatic tools in dry places away from water.
- Always use original spare parts.
- Repairs can be performed only by authorised staff people authorised by Unior d.d.



- Always disconnect tools not in use from the air supply.