

# Brusilica čeona pneumatska

1516



## Profili



## Atributi proizvoda

- broj okretaja u slobodnom hodu: 25000/min
- max. pritisak zraka: 6, 2 bara
- potrošnja zraka: 113 l/min
- priključak za zrak: 1/4"
- promjer čahure: 6 mm
- unutrašnji promjer cijevi: 10 mm


## Prednosti:

- sigurnosna ručica sprječava slučajno uključivanje alata
- jednostavno postavljanje malih reznih ploča (brusnih/polirnih čepova)
- izuzetna snaga
- lagan i kompaktan alat
- stupanjska regulacija brzine okretaja

## Upotreba:

- precizno brušenje

- potpuno brušenje
- industrija alata
- automobilska industrija
- avionska industrija
- čišćenje varova
- čišćenje betonskih površina i zidova
- čišćenje drvenih površina
- odstranjivanje boja i lakova
- odstranjivanje hrđe
- brušenje ležajeva
- brušenje ventila motora
- brušenje zupčanika i navoja
- razne druge pripreme površina



617731

L

155

A

60



390

\* Slike proizvoda su simbolične. Sve dimenzije su u mm, masa je u g.

## Upotreba (pictures)



## Photo (pictures)



## Accessories



Spojnica muška



Spojnica muška



Spojnica ženska



Spojnica ženska



Pripremna grupa 3/8"



Pripremna grupa 1/2"



Crijevo spiralno za zrak

## Safety tips



- The pressure in the tool during the operation has to be at least 6.2 bar for the tool to work properly.
- Regularly clean and dry the air filters and inlet air supply.
- Always use clean and dry air with the correct mixture of oil, for maximum tool life.
- Check the joints and ensure that the tubes and other equipment are not damaged before use.
- All tools should be gently oiled prior to being stored.
- Always store pneumatic tools in dry places away from water.
- Always use original spare parts.
- Repairs can be performed only by authorised staff people authorised by Unior d.d.



- Always disconnect tools not in use from the air supply.