

# Brusilica pneumatska kutna

1516A



## Profilii



## Atributi proizvoda


- 20.000 o/min u slobodnom hodu
- max. pritisak zraka: 6, 2 bara
- potrošnja zraka: 113 l/min
- priključak za zrak: 1/4"
- promjer čahure: 6 mm
- unutrašnji promjer cijevi: 10 mm

## Prednosti:

- ova kutna brusilica omogućuje pristup teško dostupnim mjestima
- sigurnosna ručica sprječeva slučajno uključivanje alata
- jednostavno postavljanje malih reznih ploča (brusnih/polirnih čepova)
- izuzetna snaga
- lagan i kompaktan alat
- stupanjska regulacija brzine okretaja

## Upotreba:

- precizno brušenje
- potpuno brušenje
- industrija alata
- automobilska industrija
- avionska industrija
- čišćenje varova
- čišćenje betonskih površina i zidova
- čišćenje drvenih površina
- odstranjivanje boja i lakova
- odstranjivanje hrđe
- brušenje ležajeva
- brušenje ventila motora
- brušenje zupčanika i navoja
- razne druge pripreme površina



	L	A	
--	---	---	--

617732

162

76

740

\* Slike proizvoda su simbolične. Sve dimenzije su u mm, masa je u g.

## Upotreba (pictures)



## Photo (pictures)



## Accessories



Spojnica muška



Spojnica muška



Spojnica ženska



Spojnica ženska



Pripremna grupa 3/8"



Pripremna grupa 1/2"



Crijevo spiralno za zrak

## Safety tips



- The pressure in the tool during the operation has to be at least 6.2 bar for the tool to work properly.
- Regularly clean and dry the air filters and inlet air supply.
- Always use clean and dry air with the correct mixture of oil, for maximum tool life.
- Check the joints and ensure that the tubes and other equipment are not damaged before use.



- Always disconnect tools not in use from the air supply.

- All tools should be gently oiled prior to being stored.
- Always store pneumatic tools in dry places away from water.
- Always use original spare parts.
- Repairs can be performed only by authorised staff people authorised by Unior d.d.