

数据表 uniortools.com

# 电子钢丝钳

#### 406/4E




配置文件

Premium flex 🕂 🧇

产品属性

- 材料:特种工具钢
- 落锻,完全淬火与回火
- 切削刃感应淬火
- 重型复合材料手柄



	L	В	С	А	<b>1</b>
620069	120	13.6	15.8	8.2	90

#### cutting capacity (10N=1kg)

	max	750 N/mm² <b>ØŤ</b>
620069	120	1,5

\* Images of products are symbolic. All dimensions are in mm, and weight in grams. All listed dimensions may vary in tolerance.

#### 用途 (pictures)



#### Photo (pictures)













### Safety tips

## $\checkmark$

• Pliers should be oiled regularly. A drop of oil at the hinge will lengthen the tool life and assure easy operation.

• When cutting wire with pliers, you should always wear glasses or goggles.

• Handles are provided for comfort. They are not intended to give user any degree of protection against electric shocks and should never be used on live electric circuits.

### $\bigotimes$

• Don't use pliers for cutting hardened wire, unless specifically manufactured for this purpose.

• Don't expose pliers to excessive heat. This may ruin the tool.

• Don't use pliers as a hammer.

• Don't hammer on the handles. They may crack or break.

• Don't extend the length of plier handles to secure greater leverage.

• Don't use pliers on nuts or bolts. A wrench will do a better job and with less risk of damage to the fastener.