

# Clește combinat pentru electroniști

406/4E




## Profile



## Caracteristicile produsului

- material: compoziție specială pentru calire revenire
- tratat complet
- partile tăietoare tratate prin inducție
- manere bimaterial pentru condiții grele





L

B

C

A



620069

120

13.6

15.8

8.2

90

capacitatea de taiere (10N=1kg)



L

max 750 N/mm<sup>2</sup>Ø†

620069

120

1,5

\* Imaginea produsului este simbolica.Toate dimensiunile sunt exprimate în mm,greutatea în grame.

0 (pictures)



Photo (pictures)





## Safety tips



- Pliers should be oiled regularly. A drop of oil at the hinge will lengthen the tool life and assure easy operation.
- When cutting wire with pliers, you should always wear glasses or goggles.
- Handles are provided for comfort. They are not intended to give user any degree of protection against electric shocks and should never be used on live electric circuits.



- Don't use pliers for cutting hardened wire, unless specifically manufactured for this purpose.
- Don't expose pliers to excessive heat. This may ruin the tool.
- Don't use pliers as a hammer.
- Don't hammer on the handles. They may crack or break.
- Don't extend the length of plier handles to secure greater leverage.
- Don't use pliers on nuts or bolts. A wrench will do a better job and with less risk of damage to the fastener.