

# Račna pneumtaska 1/4"

1522



## Profilii



1/4"



## Atributi proizvoda

- slobodna brzina 200 obrtaja/minutu
- max. obrtni moment 41 Nm
- preporučeni pritisak vazduha: 6, 2 bara
- potrošnja vazduha 113 l / min
- priključak za zrak: 1/4"


## Prednosti:

- uska glava
- kuglični ležaj
- gumirana ručka
- novi sistem regulacije zraka
- 360 ° dovod vazduha za okretanje
- zadnji izduvni sistem
- niski šum 79dB (A)
- mali i kompaktan alat
- kvalitetna proizvodnja
- praktičan prekidač za uključivanje

- brzo i praktično podešavanje smijera rotacije

## Upotreba:

- automobilска индустрија
- авионарска индустрија
- пољопривредна мешовитост
- тешка индустрија
- већи грађевински струјници
- бродоградња
- индивидуална монтажа
- Важно!
- препоручује се коришћење Uniorovih IMPACT насадних кључева



		L	A	B		
627565	1/4"	196	49	40,8	41	749

\* Slike proizvoda su simbolične. Sve dimenzije su u mm, masa je u g.

## Photo (pictures)



## Accessories



Spojnica muška



Spojnica ženska



Crijevo spiralno za zrak



Pripremna grupa 1/4"

## Safety tips



- The pressure in the tool during the operation has to be at least 6.2 bar for the tool to work properly.
- Regularly clean and dry the air filters and inlet air supply.
- Always use clean and dry air with the correct mixture of oil, for maximum tool life.
- Check the joints and ensure that the tubes and other equipment are not damaged before use.
- All tools should be gently oiled prior to being stored.
- Always store pneumatic tools in dry places away from water.
- Always use original spare parts.
- Repairs can be performed only by authorised staff people authorised by Unior d.d.



- Always disconnect tools not in use from the air supply.