

# “理想”型铁皮剪

568L/7P




## 配置文件



## 产品属性

- 材料：特种工具钢
- 锻造
- 刀刃感应淬火
- 落锻，完全淬火与回火
- 头表面处理：细磨
- 防腐蚀保护
- 浸塑料手柄
- 重开弹簧
- 以400N/mm<sup>2</sup>的力剪切最大厚度1.5mm的钣金



L

C





610945

L

250

C

30



532

\* Images of products are symbolic. All dimensions are in mm, and weight in grams. All listed dimensions may vary in tolerance.

## Safety tips



- Be careful of sharp edges on the cutting edges of these tools.
- Use only hand pressure for cutting.
- Snips should be carefully put away after use. Wipe the cutting edges with a lightly oiled rag.
- Oil the pivot bolt on the snips occasionally.



- Don't try to cut sharp curves with straight cut snips.
- Don't sharpen a snip blade.
- Don't use snips as a hammer, screwdriver or pry bar. Use proper tools for the job.
- Don't store snips in a drawer with other tools. Tools with cutting edges should always be treated with extra respect.
- Never hammer, or use your foot to get extra pressure on the cutting edges.

## Frequently asked questions

### Can a left-handed person use right-handed cutters?

Yes, the left-handed or right-handed scissors are intended for the direction of the radius cut.