

Гарнитура TBI навртувачи во SOS влошка

964ECO9



Profiles




Product features

- Димензија на влошката : 498 x 135 x 30 mm
- Компатибилни со фиоките на Economic

Гарнитурата вклучува:

- 4 ТВІ плоснати одвртувачи (артикл 605ТВІ) димензија 0.5х3.0х80, 0.8х4.0х100, 1.0х5.5х125, 1.2х6.5х150
- 3 ТВІ одвртувач крстач РН (артикл 615ТВІ) димензија РН 0x60, РН 1x80, РН 2x100
- 1 ТВІ одвртувач со двоен крстач (PZ) димензија PZ 2x100



Product name SKU Article Dimensions Quantity

Product name	SKU	Article	Dimensions	Quantity
Гарнитура ТВІ навртувачи во SOS влошка	621292	964ECO9	-	8
Одвртувач плоснат ТВІ изведба		605TBI	0.5 x 3.0x80, 0.8 x 4.0x100, 1.0 x 5.5x125, 1.2 x 6.5x150	4
Одвртка крстач (PH) ТВІ изведба	•	615TBI	PH 0x60, PH 1x80, PH 2x100	3
Одвртка кратка со двоен крстач (PZ)облик ТВІ изведба		625TBI	PZ 2x100	1
SOS влошка за 964ECO9		vl964ECO9	498x135x30	1

^{*} Сликите на производите се симболични. Сите димензии се во мм, тежината е во грамови. Сите наведени димензии може да се разликуваат во ниво на толеранција

Safety tips



- Use a screw holding screwdriver to get screws started in awkward, hard-to-reach areas.
- Use a stubby screwdriver in close quarters where a conventional screwdriver cannot be used.
- A rounded tip should be redressed with a file; make sure edges are straight.
- Screwdrivers used in the shop are best stored in a rack. This way, the proper selection of the right screwdriver can be quickly made.
- Keep the screwdriver handle clean; a greasy handle is apt to cause accidents.
- A screwdriver should never be used as pry bar. If it is overstressed in this manner, the blade might break and send a particle of steel into the operator's arm or even towards his eyes.



- Don't use pliers on the handle of a screwdriver to get extra turning power. A wrench should only be used on the square shank or bolster of a screwdriver that is especially designed for that purpose.
- Don't expose a screwdriver blade to excessive heat as it may reduce the hardness of the blade.
- Don't use a screwdriver with a split or broken handle.
- Don't use a regular screwdriver to check a storage battery or to determine if an electrical circuit is live.