

通用铁皮剪

563R/7PR



配置文件



产品属性

- 材料:特种工具钢
- 落锻,完全淬火与回火
- 刀刃感应淬火
- 防腐蚀保护
- 浸塑料手柄

用途:

• 以400N/mm²的力剪切最大厚度1.5mm的钣金



	L	С	1
615037	280	47	567

* Images of products are symbolic. All dimensions are in mm, and weight in grams. All listed dimensions may vary in tolerance.

Safety tips

\checkmark



• Be careful of sharp edges on the cutting edges of these tools.

• Use only hand pressure for cutting.

• Snips should be carefully put away after use. Wipe the cutting edges with a lightly oiled rag.

• Oil the pivot bolt on the snips occasionally.

• Don't try to cut sharp curves with straight cut snips.

• Don't resharpen a snip blade.

• Don't use snips as a hammer, screwdriver or pry bar. Use proper tools for the job.

• Don't store snips in a drawer with other tools. Tools with cutting edges should always be treated with extra respect.

• Never hammer, or use your foot to get extra pressure on the cutting edges.

Frequently asked questions

Can a left-handed person use right-handed cutters?

Yes, the left-handed or right-handed scissors are intended for the direction of the radius cut.