

# 直铁皮剪

573/7P






## 配置文件





## 产品属性

- 材料：特种工具钢
- 锻造
- 刀刃感应淬火
- 浸塑料手柄



	L	C	
615158	175	40	265
615159	200	40	318
615160	250	51	497

	L	C	
615161	300	70	627
615162	350	76	802

\* Images of products are symbolic. All dimensions are in mm, and weight in grams. All listed dimensions may vary in tolerance.

## Safety tips



- Be careful of sharp edges on the cutting edges of these tools.
- Use only hand pressure for cutting.
- Snips should be carefully put away after use. Wipe the cutting edges with a lightly oiled rag.
- Oil the pivot bolt on the snips occasionally.



- Don't try to cut sharp curves with straight cut snips.
- Don't sharpen a snip blade.
- Don't use snips as a hammer, screwdriver or pry bar. Use proper tools for the job.
- Don't store snips in a drawer with other tools. Tools with cutting edges should always be treated with extra respect.
- Never hammer, or use your foot to get extra pressure on the cutting edges.