

Çelës i thethësisë me dorez TBI

629TBI





Profiles



Product features

- teh: çeliku krom-molibden vanadium-, thekur tërësisht dhe nevrrik
- krom kromuar teh
- trajtuar: formë ergonomik
- tre material komponent
- varur vrimë
- bërë sipas standardit DIN 3125



|  |  | C | L | D |  |
|--|---|-----|-----|-----|---|
| 611746 | 5 | 125 | 235 | 5,2 | 92 |
| 612672 | 5.5 | 125 | 235 | 5,2 | 103 |
| 611747 | 6 | 125 | 235 | 5,2 | 103 |
| 611748 | 7 | 125 | 245 | 6,2 | 123 |
| 611749 | 8 | 125 | 245 | 6,2 | 140 |

|  |  | C | L | D |  |
|---|--|-----|-----|-----|--|
| 611750 | 9 | 125 | 245 | 6,2 | 155 |
| 611751 | 10 | 125 | 245 | 8,2 | 157 |
| 611752 | 11 | 125 | 245 | 8,2 | 166 |
| 611753 | 12 | 125 | 245 | 9,2 | 184 |
| 611754 | 13 | 125 | 245 | 9,2 | 186 |

* Imazhet e produkteve janë simbolike. Të gjitha dimensionet janë në mm, pesha në gram. Të gjitha dimensionet e listuara mund të ndryshojnë në tolerancë.

Usage (pictures)



Safety tips



- Use a screw holding screwdriver to get screws started in awkward, hard-to-reach areas.
- Use a stubby screwdriver in close quarters where a conventional screwdriver cannot be used.
- A rounded tip should be redressed with a file; make sure edges are straight.
- Screwdrivers used in the shop are best stored in a rack. This way, the proper selection of the right screwdriver can be quickly made.
- Keep the screwdriver handle clean; a greasy handle is apt to cause accidents.
- A screwdriver should never be used as pry bar. If it is overstressed in this manner, the blade might break and send a particle of steel into the operator's arm or even towards his eyes.



- Don't use pliers on the handle of a screwdriver to get extra turning power. A wrench should only be used on the square shank or bolster of a screwdriver that is especially designed for that purpose.
- Don't expose a screwdriver blade to excessive heat as it may reduce the hardness of the blade.
- Don't use a screwdriver with a split or broken handle.
- Don't use a regular screwdriver to check a storage battery or to determine if an electrical circuit is live.