

# Mágnesező/lemágnesező

633



## Profilok

---



## Termékjellemzők

- anyaga: ABS
- kék színű


## Használat:

- Az eszköz segítségével a csavarhúzó hegye mágnesezhető, így a csavarok a hegyen maradnak. A mágnesezéshez toljuk át a csavarhúzó szárát az eszköz + jelöléssel ellátott nyílásán. A csavarhúzó hegye azonnal mágnesessé válik.
- A hegyet lemágnesezhetjük, ha a csavarhúzó szárát az eszköz – jelölésű nyílásán toljuk át, illetve a nyílás belső falához érintjük.

- A mágnesesség időtartama a használat helyétől függ. Amennyiben a mágnesezett csavarhúzó olyan térben használjuk, ahol a mágneses mezők erősebbek (pl. elosztószekrény), a hegy gyorsabban demagnetizálódik. Normál környezetben a mágnesesség tovább tart.
- A mágnesezőt elsősorban olyan csavarozási feladatoknál használhatjuk, ahol a csavar egyenes behajtása nem lehetséges, viszont a csavar a csavarhúzó hegyével a furatba illeszthető. Ugyanez vonatkozik kihajtásánál is, mivel a csavar nehezen hozzáférhető helyről is eltávolítható. A mágnesezett hegyvel emellett apró fémtárgyakat is kivehetünk kézzel nem elérhető, szűk helyekről.

## Fontos!

- A mágnesezett csavarhúzó nem alkalmas rozsdamentes csavarok felvételére.



	<b>B</b>	<b>A</b>	
612866	52	30	91

\* A termékképek illusztrációk. Minden feltüntetett méret milliméterben, a tömegek grammban. Az összes feltüntetett méret eltérhet a toleranciának megfelelően.

## Safety tips



- Use a screw holding screwdriver to get screws started in awkward, hard-to-reach areas.
- Use a stubby screwdriver in close quarters where a conventional screwdriver cannot be used.
- A rounded tip should be redressed with a file; make sure edges are straight.
- Screwdrivers used in the shop are best stored in a rack. This way, the proper selection of the right screwdriver can be quickly made.
- Keep the screwdriver handle clean; a greasy handle is apt to cause accidents.
- A screwdriver should never be used as pry bar. If it is overstressed in this manner, the blade might break and send a particle of steel into the operator's arm or even towards his eyes.



- Don't use pliers on the handle of a screwdriver to get extra turning power. A wrench should only be used on the square shank or bolster of a screwdriver that is especially designed for that purpose.
- Don't expose a screwdriver blade to excessive heat as it may reduce the hardness of the blade.
- Don't use a screwdriver with a split or broken handle.
- Don't use a regular screwdriver to check a storage battery or to determine if an electrical circuit is live.