

# 欧风工具车

940E3



#### 配置文件



#### 产品属性

- 材料:金属板材
- 锁紧装置
- lock with key included also foam keyring
- 四个轮子,其中一个轮子带制动
- 滚珠轴承滑轨抽屉
- 合成材料制成的衬垫有助于抽屉和工具防损防震
- 环保无铅镉涂层
- 6个抽屉(三个尺寸为560x365x70mm,三个尺寸为560x400x150mm)

无轮静态载荷:1600公斤


车厢载荷能力:300公斤

每层抽屉载荷能力:45公斤

抽屉总容量:144升

抽屉兼容SOS工具托盘1/3,2/3,3/3

可添加挂件



	L	В	Н	L1	H1	•
608544	770	440	895	700	768	48000

<sup>\*</sup> Images of products are symbolic. All dimensions are in mm, and weight in grams. All listed dimensions may vary in tolerance.

### **Accessories**



₹ 940E和940EV小抽屉分隔套装



940E和940EV的4件分隔套装



→ 940EV纸架



940E和940EV文件架



940E和940EV瓶托



940E和940EV的ABS板




■ 940E和940EV木质板



940E和940EV螺丝刀架





## 配件



Lock with keys



Ball-bearing slide, set of 1 pair



Set of casters

## Safety tips



- Lock all your drawers before trying to roll the tool carriage into a new work area.
- Set the brakes on the locking casters after you have rolled the cabinet to your work area.
- Treat you tool carriage, tool chests, or tool boxes with respect.
- Always follow the prescribed max load capacity of individual drawers and the carriage as a whole.
- Always put heavier objects in the bottom drawers
- Always close drawers when not in use.
- Always follow manufacturer manual instructions regarding assembly and repair of your tools.



- Don't open two or more drawers at the same time, there is high chance of it tipping over.
- Don't throw tools into drawer, always put the tools in.
- Don't use an opened drawer as a working surface.
- Don't clean a lacquered surface with a solvent cleaner.
- Don't pull a tool carriage as you won't be able to see where you are headed. Push it in front of you so you can see where you are going.
- Don't stack a tool carriage with too many extra chests or tool trays; it may tip over at the most unexpected time.
- Don't roll a tool carriage with loose tools or parts on top of the carriage.
- Don't roll a tool carriage too quickly; a pot hole in the floor or some hardware on the floor may cause an accident.
- Don't overload the drawers; if you haven't got room for all of your tools, you need a larger tool carriage.
- Don't open up too many loaded drawers at a time; close each drawer before opening up another. Heavily loaded opened drawers are an invitation to tipping.