

Schroevendraaier, NI sleuf

605NI



Profielen






Standaard



DIN 5265, ISO 2380-1, 2

Product attributen

- blade: premium hard chrome vanadium steel, entirely hardened and tempered
- blade nickel plated
- handle: ergonomic shape
- handle - polypropylene
- hanging hole
- made according to standard DIN ISO 2380-1:2006 and DIN ISO 2380-2:2006



|  | axb | C | L | D |  |
|--|-----------|----|-----|-----|---|
| 616419 | 0.4 x 2.0 | 60 | 145 | 2 | 33 |
| 616420 | 0.4 x 2.5 | 75 | 160 | 2.5 | 34 |

|  | axb | C | L | D |  |
|---|------------|-----|-----|-----|--|
| 616421 | 0.5 x 3.0 | 80 | 165 | 3 | 35 |
| 616422 | 0.6 x 3.5 | 100 | 185 | 3.5 | 39 |
| 616423 | 0.8 x 4.0 | 100 | 185 | 4 | 41 |
| 616424 | 1.0 x 5.5 | 125 | 225 | 5 | 70 |
| 616425 | 1.2 x 6.5 | 150 | 250 | 6 | 103 |
| 616426 | 1.2 x 8.0 | 175 | 285 | 7 | 143 |
| 616427 | 1.6 x 10.0 | 200 | 320 | 8 | 173 |

* Afbeeldingen van producten zijn symbolisch. Alle afmetingen zijn in mm en gewicht in gram. Alle vermelde afmetingen kunnen variëren in tolerantie.

Veiligheidstips



- Use a screw holding screwdriver to get screws started in awkward, hard-to-reach areas.
- Use a stubby screwdriver in close quarters where a conventional screwdriver cannot be used.
- A rounded tip should be redressed with a file; make sure edges are straight.
- Screwdrivers used in the shop are best stored in a rack. This way, the proper selection of the right screwdriver can be quickly made.
- Keep the screwdriver handle clean; a greasy handle is apt to cause accidents.
- A screwdriver should never be used as pry bar. If it is overstressed in this manner, the blade might break and send a particle of steel into the operator's arm or even towards his eyes.



- Don't use pliers on the handle of a screwdriver to get extra turning power. A wrench should only be used on the square shank or bolster of a screwdriver that is especially designed for that purpose.
- Don't expose a screwdriver blade to excessive heat as it may reduce the hardness of the blade.
- Don't use a screwdriver with a split or broken handle.
- Don't use a regular screwdriver to check a storage battery or to determine if an electrical circuit is live.

Veiligheid (Afbeeldingen)

